

Aerial roof documentation

Contractor review sample

Capture date 29 Sep 2026 Location Montauk, New York

A dated visual record for contractor review. Numbered markers locate three observation groups and link to closer views; they do not assign severity.



Overview from photo 0086. Marker 1 appears at three locations.

01
Apparent surface water

Three visible areas
Details on page 2

02
Skylight surroundings

Visible color variation
Details on page 2

03
Straight roof band

Visible tonal change
Details on page 3

Observed roof features

The photographs record visible features at capture. A contractor can use these details to plan any on-site checks.

1 Apparent surface water



Detail from photo 0085

Visible: A dark, bounded area contains green and brown material.

Unverified: The image does not establish water depth, duration or drainage performance.

Review: Confirm conditions after a drying interval; check roof covering and outlets on site.

2 Skylight surroundings



Detail from photo 0085

Visible: Warmer-colored shingle courses surround two skylights and nearby roof penetrations.

Unverified: Color variation alone does not establish a leak or failed flashing.

Review: Check flashing, roof penetrations and relevant interior areas on site.

Reading the images: Lighting, shadows, surface color and resolution affect what is visible. These observations do not establish cause, condition severity or repair scope.

3 Straight roof band

A straight tonal band follows the geometry of the central roof area.



Detail from photo 0086. The tonal band is visible near the center.

Visible: No opening or missing material is evident in this view. The band may reflect a normal lap, coating or material change. A close on-site review is needed to identify the roof system and check the edges.

Use and limitations

Photo-only visual record. Roof size, pitch and hidden conditions are unverified. This sample provides no repair estimate, leak diagnosis, structural opinion or licensed survey.

Capture date and general location follow the supplied report. GPS refers to the camera position; no property address is provided.

Discuss a roof-documentation pilot